PRINT DATE: 04/11/98

PAGE: 1

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE NUMBER:M5-6SS-0911 -X

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0

02/27/98

PART DATA

PART NAME

PART NUMBER

VENDOR NAME

VENDOR NUMBER

ASSY : DOCKING BASE

VO76-000003

LRU

:HEATER

ME363-0060-0003

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

HEATER, 54 WATT - EXTERNAL AIRLOCK DOCKING BASE, VESTIBULE, ZONES 1, 2, AND 3.

REFERENCE DESIGNATORS:

40V64HR33

40V64HR34

40V64HR35 40V64HR36 40V64HR37

40V64HR38

QUANTITY OF LIKE ITEMS: 6

(SIX)

FUNCTION:

PROVIDES REQUIRED HEAT TO PREVENT CONDENSATION ON DOCKING BASE WALLS

REFERENCE DOCUMENTS:

1) VS70-640109, SCHEMATIC DIAGRAM - AIRLOCK

ENVIRONMENTAL CONTROL SUBSYSTEM

PRINT DATE: 04/11/98 PAGE 5

FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE

NUMBER: M5-6SS-0911-02

REVISION#: 0

02/27/98

SUBSYSTEM NAME: ISS DOCKING SYSTEM

LRU: DOCKING BASE ITEM NAME: HEATER CRITICALITY OF THIS FAILURE MODE: 1R3

FAILURE MODE:

SHORT END TO END, SHORT TO GROUND

MISSION PHASE:

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

103 DISCOVERY

104 ATLANTIS 105 ENDEAVOUR

CAUSE:

A) PIECE PART FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) PASS

C) PASS

PASS/FAIL RATIONALE:

A)

B)

C)

METHOD OF FAULT DETECTION:

REVIEW OF HEATER CIRCUIT TELEMETRY DATA

MASTER MEAS, LIST NUMBERS:

V64T0133A

V64T0134A

FAILURE MODES EFFECTS ANALYSIS (FMEA) — NON-CIL FAILURE MODE NUMBER: M5-6SS-0911-02

CORRECTING ACTION: MANUAL

CORRECTING ACTION DESCRIPTION:

CREW WILL ACTIVATE REDUNDANT HEATER CIRCUIT.

- FAILURE EFFECTS -

(A) SUBSYSTEM:

POWER SIDE OF FIRST HEATER SHORTS TO GROUND - SERIES FUSE OPENS PROTECTING MAIN BUS. LOSS OF ONE HEATER CIRCUIT IN ZONE. REDUNDANT HEATER CIRCUIT IN ZONE PROVIDES REQUIRED HEAT.

(B) INTERFACING SUBSYSTEM(S):

FIRST FAILURE - NO EFFECT

(C) MISSION:

FIRST FAILURE - NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW/VEHICLE AFTER THREE FAILURES:

- 1) POWER SIDE OF FIRST HEATER SHORTS TO GROUND SERIES FUSE IN HEATER CIRCUIT OPENS PROTECTING MAIN BUS. LOSS OF ONE HEATER CIRCUIT IN AFFECTED ZONE. THE ASSOCIATED CIRCUIT BREAKER (A) IS OPENED AND THE REDUNDANT HEATER CIRCUIT BREAKER (B) IS CLOSED TO RESTORE HEATING IN THE AFFECTED ZONE.
- 2) GENERAL PURPOSE RELAY (B) IN REDUNDANT HEATER CIRCUIT FAILS OPEN LOSS OF POWER TO REDUNDANT HEATERS IN ALL THREE ZONES.
- 3) CIRCUIT BREAKER (A) FAILS OPEN DURING ATTEMPT TO RE-ENERGIZE THE REMAINING INTACT (A) HEATERS RESULTING IN LOSS OF ALL HEATING CAPABILITY. POTENTIAL CONDENSATION ON EXTERNAL AIRLOCK WALLS RESULTS IN WATER IN EXTERNAL AIRLOCK. WATER MIGRATION TO KEEL AREA COULD RENDER RUSSIAN AVIONICS INOPERATIVE AFTER DOCKING, RESULTING IN LOSS OF NOMINAL AND PYROTECHNIC UNDOCKING CAPABILITY.

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F));

(F) RATIONALE FOR CRITICALITY DOWNGRADE:

ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKAROUNDS CONSIDERATION (ALLOWED PER CR S050107W), THEY ARE PROVIDING ADDITIONAL FAULT TOLERANCE TO THE SYSTEM.

PAGE: 7 PRINT DATE: 04/11/98

FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: M5-6SS-0911-02

AFTER THE THIRD FAILURE, THE CREW WOULD PERFORM EVA TO REMOVE 98 BOLTS FROM THE DOCKING BASE TO CIRCUMVENT THE WORST CASE "DESIGN CRITICALITY" EFFECT. IF UNABLE TO PERFORM EVA (FOURTH FAILURE), POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF ALL UNDOCKING CAPABILITY.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: HOURS

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: HOURS

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?
YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:
DESIGN FAULT TOLERANCE: POSSIBLE LOSS OF VESTIBULE HEATING AFTER THREE
FAILURES. AFTER THE THIRD FAILURE, THE CREW CAN PERFORM EVA TO REMOVE 96
BOLTS FROM THE DOCKING BASE TO UNDOCK.

HAZARD REPORT NUMBER(\$): ORBI 401

HAZARD(S) DESCRIPTION:

INABILITY TO SAFELY SEPARATE ORBITER FROM A MATED ELEMENT.

- APPROVALS -

SS&PAE

DESIGN ENGINEERING

: T. K. KIMURA

: C. J. ARROYO